PHSEN Tech Refresh & Quality Assessment

OOI MIO Instrument & Data Teams

Instrument Tech Refresh Prioritization

OOI 2.0 – Instrument Tech Refresh Prioritization												
			1 = good, 2 = adequate, 3 = bad					1 = not anytime soon, 2 = next few years, 3 = now		1 = none, 2 = one, 3 = more than one		
Instrument Class	- Model 	Vendor -	Data Quality -	Relia- bility	Ease of Use	Safety 👳	Vendor _ Quality _	Obsolescence =	Alternative from same 	COTS Alternatives	Alternative	Sum =
CAMDS		Kongsberg	2	3	3	2	3	3		2	No	18
PHSEN	SAMI-pH	Sunburst	2	2	3	3	3	1	No	3	No	17
PCO2W	SAMI-CO2	Sunburst	2	2	2	3	3	1	No	3	No	16
VEL3D-B	MAVS	Nobska Scientific	2	2	2	1	3	1	No	3	Yes	14
ΟΡΤΑΑ	AC-S	WET Labs	2	3	3	1	2	1	No	1	No	13
DOFST	SBE43	Sea-Bird	2	2	2	1	1	1	Yes	3	No	12
ZPLSC/G	AZFP	ASL	2	2	1	1	2	1	No	2	Yes	11
WAVSS	Tri-Axys	Axys Technologies	1	1	2	1	1	3	No	2	No	11
PARAD	QSP	Biospherical	1	1	1	1	1	3	No	3	Yes	11
VEL3D	Aquadopp2	Nortek	2	1	1	1	1	2	Yes	3	Yes	11
VEL3D	Vector	Nortek	1	2	2	1	1	1	Yes	3	Yes	11
VELPT	Aquadopp	Nortek	1	2	2	1	1	1	No	3	No	11
PRESF	SBE26plus	Sea-Bird	1	1	1	1	1	3	No	3	No	11
ADCP	WorkHorse	Teledyne RDI	1	2	1	1	2	1	Yes	3	No	11
FDCHP	DCFS	WHOI	1	3	2	1	2	1	No	1	No	11

Instrument Tech Refresh

PHSEN

- Specification 1336-00012
 - Range: 7.3 8.5 units
 - Accuracy: ±0.01 units
 - Precision: 0.005 units
 - Annual Drift: < 0.001 units
- Selected Instrument
 - Sunburst Sensors SAMI-ph
- Quantities in OOI
 - CGSN 45
 - EA-20
 - RCA 18
- Initial procurement costs
 - CGSN/EA \$1,545,250
 - RCA \$204,750

PCO2W

- Specification 1336-00013
 - Range: 100 2,000 µatm
 - Accuracy: ±4 µatm for concentrations of ≤400 µatm, or ±1% of value for >400 µatm
 - Precision: ±2 µatm for concentrations of ≤400 µatm, or ±0.50% for >400 µatm
- Selected Instrument
 - Sunburst Sensors SAMI-CO2
- Quantities in OOI
 - CGSN 35
 - EA−12
 - RCA 14
- Initial procurement costs
 - CGSN/EA \$685,600
 - RCA \$114,400

PHSEN Instrument Issues

- Ease of Use
 - Manual flushing required before deployment to prevent air-locking
- Vendor Quality
 - Issues with incorrect wiring for inductive units
 - No controlled schematics/drawings, units not consistently manufactured to a spec
 - Buggy software
- Safety
 - Leak issues results in seawater-battery interactions and over-pressurization
 - Root cause not definitively determined likely leaking around fiber entry
 - Vent plug added to housing to allow for venting on recovery
- Reliability
 - Issues with batteries discharging quicker than anticipated
 - Housing not sufficiently robust for SUMO mooring riser deployments

PHSEN Quality Assessment

Data Availability

- All PHSEN data downloaded from OOINet via M2M
- Identified gap/missing days from Telemetered, Recovered, Streaming data
- Days Missing = Total deployment days -Number of data with data
- Opportunity Days = Total deployment days
 days of infrastructure downtime

Data Collected 71% of the total deployment time (all Arrays, all deployments)


Data Quality

- Performed on "preferred" data stream with most data – e.g., Recovered, Streaming, Telemetered
- Evaluated
 - Global Range Test of pH values
 - Range Test of blank signal at 434 and 578
 - Noise defined by point-to-point variability
- "Good" data passed all three evaluations
- % Success = Good Days / Opportunity Days

44% Success Rate (collected "good" data)

PHSEN Quality Assessment


% Success vs. Year





PHSEN Quality Assessment

% Success vs. Array




Array

PHSEN Quality Assessment – "Good" Data


GS03FLMB PHSEN Deployment 1


Seawater pH 8.5 7.5 Feb Ma Oct Nov Dec Apt May hr -bui Au Ser 2015 434 Reference 3000 2500 2000





GS03FLMB PHSEN Deployment 1







PHSEN Quality Assessment – "Bad" Data


Seawater pH


GA03FLMA PHSEN Deployment 3














PHSEN Failure Modes

INSTRUMENT ISSUES

- Firmware 3%
- Battery 37%
 - Instrument stopped before the end of the deployment
- Obstruction 28%
 - Potentially air-locked pump, or sand or other obstruction
- Lamp 5%
- Pump 9%
- Leak/Flooded 4%

EXTERNAL ISSUES

- Physical Damage 5%
 - Instruments mounted on the rise of Global Surface Moorings
- Lost 3%
 - Instruments mounted on the rise of Global Surface Moorings
- Vendor refurb timing 3%
 - Not returned in time to be deployed
- OOI Schedule 5%
 - Not enough time between cruises for refurbishment

PHSEN Instrument Issues

GS01SUMO-00004



GI01SUMO-00002



PHSEN Tech Refresh – Path Forward

COMPLETED TASKS

- Prioritized instrumentation for tech refresh
- Updated Common Instrument Specification (1336-00000)
- Drafted Instrument Tech Refresh Process
 Document
- Quality assessment of PHSEN data
- Identified potential pH instrument vendors
- Drafted RFI document

NEXT STEPS

- Evaluate PHSEN requirements w/ SME input
- Issue RFI
- Assess RFI responses
- Conduct an Analysis of Alternatives, if necessary
- Issue RFQ
- Generate recommendation plan
- Generate ECR for implementation of procurement
- Procure & Test